

INDEPENDENT SERVICE INVOICE: **35233** 5/15/2009

AUTO SHOPPE IMPORTS

1401 THIRD ST. N.W.
 ALBUQUERQUE NM 87102
 ALBUQUERQUE NM 87102

6616 Central Ave. Se
 Albuquerque NM 87108

(505) 247-9771

05142009 (505) 250-1120 p

ivs@lobo.net

**2004 Volvo V70 License: 3240/3265 Odometer: 90040 Vin: YV1SW61T342443265
 B5244S AW 55-50/51SN ABS RED**

PRESALE INSPECTION AND BASIC MAINTENANCE

Labor performed on this job:

Labor 1 Labor Rate: \$90.00 \$90.00
 INSPECT VEHICLE IN ORDER TO DETERMINE SERVICE
 NEEDS BEFORE SALE
 8

Parts: \$0.00
 Labor: \$90.00
Job Subtotal: \$90.00

SERVICE WORK

Labor performed on this job:

Labor 2.2 Labor Rate: \$90.00 \$198.00
 OIL AND FILTER SERVICE AND SERVICE
 TRANSMISSION. REPLACE RIGHT SPRAYER, RT
 LICENSE PLATE BULB, LEFT HEADLIGHT BULB, LEFT
 WIPER ARM COVER, CABIN AIR FILTER AND SPARK
 PLUGS. CHECK FAULT CODES: NONE FOUND
 1

Parts required on this job:

Haz Mat Fee	6	\$0.25	\$1.50
10W30	6	\$3.05	\$18.30
TRANSMISSION OIL	1	\$69.34	\$69.34
WASHER JET, FRONT 2/CAR V70 01-02, S60	1	\$10.48	\$10.48
BULB, INDIC/DOME/3RD BRAKE/LIC 900 86-98, 9000, 9-	1	\$4.30	\$4.30
WIPER COVER LEFT	1	\$5.72	\$5.72
FILTER, FRESH AIR CABIN S80 -06, V70 01+, S60 -09,	1	\$35.58	\$35.58
SPARKPLUG, BOSCH SUPER 850, 960, 90, C70, S/V70 -0	5	\$1.99	\$9.95
BULB, HEADLIGHT C70 -08, S	1	\$13.65	\$13.65

Parts Discount Off List Price
 \$3.15

Parts: \$168.82
 Labor: \$198.00
Job Subtotal: \$366.82

CONTROL ARM BUSHINGS, BOTH PAIRS S60

Labor performed on this job:

Labor 5 Labor Rate: \$90.00 \$450.00

Inspection of front end parts revealed both front lower control arm forward bushings have failed. Remove both lower control arms and replace failed bushings, reinstall control arms. Customer will have vehicle aligned.

8

Parts required on this job:

BUSHING, A ARM FRONT 2/CAR - STD DUTY 2 \$43.59 \$87.17

BUSHING, A ARM REAR 2 \$27.74 \$55.48

2 WHEEL ALIGNMENT... 1 \$62.95 \$62.95

Parts: \$205.60
Labor: \$450.00
Job Subtotal: \$655.60

UPPER SPRING SEAT RIGHT

Labor performed on this job:

Labor 1.5 Labor Rate: \$90.00 \$135.00

REMOVE RIGHT FRONT STRUT ASSEMBLY, DISASSEMBLE STRUT AND REPLACE UPPER SPRING SEAT. REASSEMBLE AND REINSTALL STRUT ASSEMBLY.

8

Parts required on this job:

SPRING SEAT, FOR STRUT 1 \$43.71 \$43.71

Parts: \$43.71
Labor: \$135.00
Job Subtotal: \$178.71

BRAKES, REAR WITH NEW ROTORS AND PADS

Labor performed on this job:

Labor 1.6 Labor Rate: \$90.00 \$144.00

Test drive in an attempt to duplicate customer complaint, if any. Examine wheel brakes for wear and deterioration. Replace rotors with new. Examine calipers for leakage, clean and lubricate them as needed. Treat brake pad friction surfaces with BG brand noise control compound and lubricate pad backing surfaces with copper base antiseize. Reassemble torquing all threaded hardware and test drive to verify repairs.FRONT BRAKES 90%

8

Parts required on this job:

BRAKE PAD, REAR S/V70 MID99-00 AWD, S60, V70 01+, 1 \$71.74 \$71.74

BRAKE ROTOR, REAR V70 01+, S60, S80 -06 2 \$100.72 \$201.44

Parts: \$273.18
Labor: \$144.00
Job Subtotal: \$417.18

MASTER KEY WITH SOFTWARE DOWNLOAD

Labor performed on this job:

Labor 0.5 Labor Rate: \$90.00 \$45.00

Supply new master key and download software to make it operate

1

Parts required on this job:

PASS KEY 1 \$58.75 \$58.75

IGNITION KEY APPL. 1 \$37.00 \$37.00

Parts: \$95.75
Labor: \$45.00
Job Subtotal: \$140.75

EMISSION TEST(FLEET)

Labor performed on this job:

Labor 0.1882 Labor Rate: \$90.00 \$16.94
PERFORM BERNILLO COUNTY EMISSION TEST
1

Parts: \$0.00
Labor: \$16.94
Job Subtotal: \$16.94

FUEL DOOR HINGE

Labor performed on this job:

Labor 0.0000 Labor Rate: \$90.00 \$0.00
REPLACE FUEL DOOR HINGE
1

Parts required on this job:

HINGE, GAS DOOR S60, S80, 1 \$8.59 \$8.59

Parts: \$8.59
Labor: \$0.00
Job Subtotal: \$8.59

SHOP INFORMATION AND SUPPORT

Labor performed on this job:

Labor 0.43 Labor Rate: \$90.00 \$38.70

The information age has arrived and it is expensive. We currently spend in excess of \$1000 monthly for current Volvo service information and hardware associated with its use. Additionally, the myriad of items never invoiced i.e. Hardware, chemicals, cleaner and other supplies continue to escalate in cost. Our shuttle service is another new expense. This surcharge is to help recover a portion of these costs without increasing our labor rate. Thank you for your understanding and support.

9

Parts: \$0.00
Labor: \$38.70
Job Subtotal: \$38.70

Invoice Summary

Parts: \$795.65
Labor: \$1,117.64
Discounts: (\$226.93)
Subtotal: \$1,913.29
Tax: \$0.00
Total: \$1,686.36

I, the registered owner, hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. I agree to pay reasonable storage on vehicles left more than 48 hours after notification of completion of repairs. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs, storage, and any legal fees thereto. I agree to pay costs of any attorney of collection fees. Payment is due at completion of work. Any returned check is subject to a 35.00 charge. All past due accounts are subject to a 1.5% monthly late fee. Smog: Some Emission control devices may be covered under warranty. By law you may choose another facility to perform any need repairs or adjustments which the smog tests indicates are necessary. All parts and labor carry a 12 month or 12,000 mile warranty.