

INDEPENDENT SERVICE Estimate: **36512** 8/5/2009

AUTO SHOPPE IMPORTS

1401 THIRD ST. N.W.
ALBUQUERQUE NM 87102
ALBUQUERQUE NM 87102

6616 Central Ave. Se
Albuquerque NM 87108

(505) 247-9771

08042009 (505) 250-1120 p

ivs@lobo.net

**2004 Volvo V70 License: 3255/6584 Odometer: 74029 Vin: YV1SW61T242396584
B5244S AW55/50-51SN ABS SILVER MET**

PRESALE INSPECTION AND BASIC MAINTENANCE

Labor performed on this job:

Labor 1 Labor Rate: \$90.00 \$90.00
INSPECT VEHICLE IN ORDER TO DETERMINE SERVICE
NEEDS BEFORE SALE

8

Parts: \$0.00
Labor: \$90.00
Job Subtotal: \$90.00

SERVICE WORK

Labor performed on this job:

Labor 3.3 Labor Rate: \$90.00 \$297.00

Oil and filter service. Replace air filter, cabin air filter, spark plugs, left lower taillight bulb, right mirror glass, upper engine stabilizer bushing, rear windshield washer jet and all wipers.

8

Parts required on this job:

Haz Mat Fee	6	\$0.25	\$1.50
10W30	6	\$3.05	\$18.30
WASHER, DRAIN PLUG - ALUMINIUM 850, 960, 70, 90, S	1	\$0.86	\$0.86
GASKET, OIL FILLER CAP 200 4CYL, 700 4CYL, 900, 85	1	\$1.75	\$1.75
AIR FILTER, V70 01+, S60, S80 04-06 5CYL	1	\$29.02	\$29.02
FILTER, FRESH AIR CABIN S80 -06, V70 01+, S60 -09,	1	\$35.58	\$35.58
SPARKPLUG, BOSCH SUPER 850, 960, 90, C70, S/V70 -0	5	\$1.99	\$9.95
BULB, TAIL LIGHT (OFFSET PINS 2 FILAMENT) VOLVO> C	1	\$3.26	\$3.26
GLASS, RIGHT	1	\$80.82	\$80.82
TORQUE MOTOR MOUNT, UPPER TO STAY ROD (KEY SLOT) C	1	\$69.04	\$69.04
WASHER NOZZLE	1	\$8.67	\$8.67
WIPER BLADE KIT, FRONT (2 PCS) V70 01-04, S60 -04,	1	\$40.35	\$40.35
WIPER BLADE, REAR V70 MID03+, XC70 MID03+	1	\$16.46	\$16.46
WIPER BLADE KIT, HEADLIGHT (2PC) V70 01+, S60	1	\$14.53	\$14.53

Parts: \$330.09

Labor: \$297.00

Job Subtotal: \$627.09

AIR CONDITIONING

Labor performed on this job:

Labor 3 Labor Rate: \$90.00 \$270.00

Replace a/c compressor clutch bearing. Evacuate and recharge system

8

Parts required on this job:

P2 A/C COMPRESSOR CLUTHCH BEARING, USED	1	\$15.00	\$15.00
---	---	---------	---------

Parts: \$15.00

Labor: \$270.00

Job Subtotal: \$285.00

FRONT SUSPENSION- LOWER CONTROL ARM BUSHINGS (P2)

Labor performed on this job:

Labor 5 Labor Rate: \$90.00 \$450.00

Parts required on this job:

BUSHING, A ARM 2 \$43.59 \$87.17
FRONT - HEAVY DUTY

Inspect suspension. Remove lower control arms, press damaged front and rear bushings out and install new bushings using hydraulic press. Reinstall control arms and test drive.

BUSHING, A ARM REAR 2 \$27.74 \$55.48

8

Parts: \$142.65

Labor: \$450.00

Job Subtotal: \$592.65

EMISSION TEST(FLEET)

Labor performed on this job:

Labor 0.1882 Labor Rate: \$90.00 \$16.94

PERFORM BERNILILLO COUNTY EMISSION TEST

1

Parts: \$0.00

Labor: \$16.94

Job Subtotal: \$16.94

SHOP INFORMATION AND SUPPORT

Labor performed on this job:

Labor 0.43 Labor Rate: \$90.00 \$38.70

The information age has arrived and it is expensive. We currently spend in excess of \$1000 monthly for current Volvo service information and hardware associated with its use. Additionally, the myriad of items never invoiced i.e. Hardware, chemicals, cleaner and other supplies continue to escalate in cost. Our shuttle service is another new expense. This surcharge is to help recover a portion of these costs without increasing our labor rate. Thank you for your understanding and support.

9

Parts: \$0.00

Labor: \$38.70

Job Subtotal: \$38.70

Estimate of Repair

Parts: \$487.74

Labor: \$1,162.64

Discounts: **(\$198.05)**

Subtotal: \$1,650.38

Tax: \$0.00

Total: \$1,452.33