

# INDEPENDENT SERVICE

3/16/2010

Estimate: 39444

## AUTO SHOPPE IMPORTS

1401 THIRD ST. N.W.  
ALBUQUERQUE NM 87102  
ALBUQUERQUE NM 87102

6616 Central Ave. Se  
Albuquerque NM 87108

(505) 247-9771

02262010 (505) 250-1120 p

ivs@lobo.net

2004 Volvo S60 License: 3288/3336 Odometer: 109930 Vin: YV1RH52Y242333336  
B5244T4 M66AWD CHARCOAL

### MASTER KEY WITH SOFTWARE DOWNLOAD

Labor performed on this job:

Labor 0.5 Labor Rate: \$90.00 \$45.00  
Supply new master key and download software to make it  
operate  
1

Parts required on this job:

PASS KEY	1	\$63.47	\$63.47
IGNITION KEY APPL.	1	\$37.00	\$37.00

Parts: \$100.47  
Labor: \$45.00  
**Job Subtotal:** \$145.47

### PRESALE INSPECTION AND BASIC MAINTENANCE

Labor performed on this job:

Labor 1 Labor Rate: \$90.00 \$90.00  
INSPECT VEHICLE IN ORDER TO DETERMINE SERVICE  
NEEDS BEFORE SALE  
8

Parts: \$0.00  
Labor: \$90.00  
**Job Subtotal:** \$90.00

### SERVICE WORK

Labor performed on this job:

Labor 3.2 Labor Rate: \$90.00 \$288.00  
Oil and filter service. Replace license plate bulbs, cabin air  
filter, wiper blades, center console box, fuel filler cap and  
lower windshield trim end pieces and trim clips. Repaired  
driver's mirror motor. Check fault codes: none found.  
8

Parts required on this job:

Haz Mat Fee	6	\$0.25	\$1.50
10W30	6	\$3.10	\$18.60
OIL FILTER, INSERT 70 99-04 V70 99+, S80 99- 06 V8 -09 , S40 -MID04, V40 -04, S60 01-09, XC90 03-09 (EXC 07+ 6CYL)	1	\$10.92	\$10.92
WASHER, DRAIN PLUG - ALUMINIUM 850, 960, 70, 90, S80, 40, V50, S60, XC90	1	\$0.43	\$0.43
GASKET, OIL FILLER CAP 200 4CYL, 700 4CYL, 900, 850, 90	1	\$2.74	\$2.74
BULB, INDIC/DOME/3RD BRAKE/LIC 900 86-98, 9000, 9-3 -07, 9-5 -07	2	\$4.30	\$8.60
FILTER, FRESH AIR CABIN S80 -06, V70 01+, S60, XC90	1	\$35.41	\$35.41
WIPER BLADE KIT, FRONT (2 PCS) V70 01-	1	\$39.73	\$39.73

04, S60 -04, S80 -03,  
XC90 -04

STORAGE TRAY	1	\$131.52	\$131.52
CLIP	2	\$2.62	\$5.24
CLIP, MOULDING RAIN TRIM V70 01+, S60	6	\$2.62	\$15.72
END PIECE, RIGHT	1	\$8.19	\$8.19
END PIECE, LEFT	1	\$8.19	\$8.19
FUEL FILLER CAP	1	\$28.76	\$28.76

Parts: \$315.55  
Labor: \$288.00  
**Job Subtotal:** \$603.55

## BRAKE PAD REPLACEMENT, P2 CHASSIS, FRONT

Labor performed on this job:

Labor 1 Labor Rate: \$90.00 \$90.00

Parts required on this job:

FRONT BRAKE PAD  
SET V70R AWD -00 1 \$84.81 \$84.81

Test drive to check for brake pulsation. Examine calipers for leakage, clean and lubricate them as needed. Treat brake pad friction surfaces with BG brand noise control compound and lubricate pad backing surfaces with copper base antiseize. Install brake pad set in calipers. Reassemble torquing all threaded hardware and test drive to verify repairs. Rear brakes: 50% remaining.

8

Parts: \$84.81  
Labor: \$90.00  
**Job Subtotal:** \$174.81

## ALTERNATOR NOISEY

Labor performed on this job:

Labor 3.5 Labor Rate: \$90.00 \$315.00

Parts required on this job:

ALTERNATOR FRONT  
BEARING S/V 70 1 \$36.75 \$36.75

Remove and disassemble alternator, replace noisy front bearing, reassemble alternator and reinstall. Verify operation of charging system.

8

Parts: \$36.75  
Labor: \$315.00  
**Job Subtotal:** \$351.75

## EMISSION TEST(FLEET)

Labor performed on this job:

Labor 0.1882 Labor Rate: \$90.00 \$16.94

PERFORM BERNILLO COUNTY EMISSION TEST

1

Parts: \$0.00  
Labor: \$16.94  
**Job Subtotal:** \$16.94

## SHOP INFORMATION AND SUPPORT

Labor performed on this job:

Labor 0.42 Labor Rate: \$90.00 \$37.80

The information age has arrived and it is expensive. We currently spend in excess of \$1000 monthly for current Volvo service information and hardware associated with its use. Additionally, the myriad of items never invoiced i.e. Hardware, chemicals, cleaner and other supplies continue to escalate in cost. Our shuttle service is another new expense. This surcharge is to help recover a portion of these costs without increasing our labor rate. Thank you for your understanding and support.

9

Parts:	\$0.00
Labor:	\$37.80
<b>Job Subtotal:</b>	<b>\$37.80</b>

### Estimate of Repair

Parts:	\$537.58
Labor:	\$882.74
Discounts:	<b>(\$170.44)</b>
Subtotal:	\$1,420.32

Tax:	\$0.00
<b>Total:</b>	<b>\$1,249.88</b>

